


130649

UNITED STATES GENERAL ACCOUNTING OFFICE
WASHINGTON, D.C. 20548

FOR RELEASE ON DELIVERY
Expected at 10:00 a.m.
August 8, 1986

STATEMENT OF
BILL W. THURMAN
DEPUTY DIRECTOR, NATIONAL SECURITY AND
INTERNATIONAL AFFAIRS DIVISION,
U.S. GENERAL ACCOUNTING OFFICE
BEFORE THE
COMMITTEE ON ENERGY AND COMMERCE
SUBCOMMITTEE ON OVERSIGHT AND INVESTIGATIONS
HOUSE OF REPRESENTATIVES
ON
IMPROPER DISPOSAL OF
REPAIRABLE AND SERVICEABLE PARTS
FOR F100 JET ENGINES BY THE AIR FORCE



130649

036295

Mr. Chairman, Members of the Subcommittee:

We are pleased to be here today to discuss our ongoing review, which we are conducting at your request, of actions taken by the Air Force to prevent the premature disposal of spare parts and other materials needed to support active weapons systems.

In response to the Air Force Inspector General's findings that usable property was erroneously being sent to disposal, the Air Force imposed a disposal moratorium in March 1984. The moratorium was to remain in effect until corrective actions could be put in place to assure that only unneeded materials were sent to disposal. The moratorium was lifted on January 1, 1986. The fundamental objective of our ongoing review is to evaluate the corrective actions taken by the Air Force.

We began our review of post moratorium disposal practices in April 1986 at the San Antonio Air Logistics Center (ALC). Shortly thereafter, we found that high cost F100 engine turbine blades in both serviceable and repairable condition, were still being improperly condemned by the Air Force and sent to the Defense Reutilization and Marketing Office (DRMO) where they are later sold as scrap metal.

THE AIR FORCE'S INSPECTION/CONDEMNATION
PROCESS FOR F100 ENGINE BLADES

The F100 engine supports the F-15 and F-16 fighter aircraft and is essential to the combat readiness of the United States. The Air Force has more than 2,900 F100 engines valued at more than \$9.3 billion. The engine is comprised of six modules, including the high pressure turbine. Within the high pressure turbine are 68 first stage and 72 second stage blades. These blades are inspected during the periodic overhaul of F100 engines by the ALC. As part of the process, engines are evaluated for signs of over temperature operations, a condition which requires that all blades within the high pressure turbine module be condemned. This is because blades that have been exposed to very high temperatures are more likely to fail, and because an over temperature blade can not be visually confirmed. Condemned blades are sent to DRMO for disposal.

If an over temperature condition does not exist, the blades are removed from the engine and those with obvious defects are condemned and sent to disposal. Blades that appear either serviceable or repairable are subjected to a series of tests. Those that pass all the tests undergo limited Air Force rework and are returned to the assembly line as serviceable. Blades found to be damaged but repairable are held for contractor repair. If the damage requires further engineering evaluation,

the blades are held until an Air Force engineering inspection team determines whether they should be condemned or held for future repair.

IMPROPER CONDEMNATION OF F100
ENGINE BLADES CONTINUES

According to DRMO records and information provided by the ALC, the improper and/or premature disposal of F100 engine blades has been a problem since 1983 and has occurred before, during, and after the disposal moratorium.

In early April 1986, we visited DRMO and observed a repair contractor employee sifting through turbine blades in the scrap metal area. The employee identified 1,259 blades that he considered repairable and 13 that he considered serviceable. The total value of these blades was about \$580,000. The contractor picked up the repairable blades the following week. ALC maintenance officials told us they did not verify the condition of the blades.

Because of the potentially serious consequences of properly condemned blades being used in overhauls, we asked the ALC to test the 13 serviceable blades identified by the contractor. Only seven of the blades were found to be serviceable. The other six blades were determined to be not repairable, and therefore had been properly condemned.

In early July 1986, ALC officials said that they had also inspected 301 first stage blades that had gone to disposal after we had discovered the usable blades in DRMO and found that 258 of these blades, with a value of over \$155,000, had been improperly condemned. Of these blades, 168 were the newer design and more expensive "showerhead" blade. ALC officials told us they are developing a repair procedure for the newer blades and the blades should have been held in stock pending the award of a repair contract. The other 90 older design blades were found to be in repairable condition.

According to an ALC official, the repeated disposal of repairable blades is the result of confusing technical data, unclear inspection guidelines, and poor inspections made by Air Force maintenance personnel.

PREVIOUSLY CONDEMNED BLADES WERE
BEING REPAIRED AND REINTRODUCED
INTO THE SUPPLY SYSTEM

ALC officials told us the contractor had screened blades in the disposal yard on four separate occasions during the last year. In a letter of appreciation to DRMO, dated February 18, 1986, the contractor stated that 3,835 blades had been recovered from scrap metal bins for repair and reuse by the Air Force. According to an ALC official, the contractor had typically requested and was given permission to screen blades in disposal when there was an inadequate supply of repairable blades; thus adversely affecting repair operations.

In an attempt to determine more precisely the number of blades removed from the disposal yard, we examined DRMO records covering the period between February 1984 and April 1986. We found that over 28,000 blades, worth about \$13.6 million, had been recalled from disposal and either shipped directly to the contractor for repair or to ALC.

REPAIRED BLADES ARE
STILL DEFECTIVE

Because of the high rejection rate of the 13 blades the contractor had considered serviceable, we asked ALC to inspect 142 blades repaired by the contractor. According to a maintenance official, these blades were ready to be used in engine overhauls.

Of the 142 blades inspected, 12 were rejected; 11 because of "thin walls" and 1 because of an "unacceptable heat code." These types of problems are related to manufacturing defects and can cause in-flight, catastrophic engine failure. According to ALC officials, these types of deficiencies should normally be identified when the blades are first removed from the engines and inspected. The Air Force should then condemn unacceptable heat code blades and send thin walled blades back to the original manufacturer for warranty exchange, in accordance with applicable technical orders and other management controls.

On July 2, 1986, the director of maintenance gave us a revised inspection report, stating that the directorate's previous inspection was incomplete. Later inspections identified 1 additional thin wall blade and 31 blades with "improper coating," bringing the total number of defective blades to 44.

Because of the problems which were identified in the blade tests and inspections we requested, ALC has begun to inspect all blades that have been repaired and are still in serviceable depot stocks for use in engine overhauls. On July 1, 1986, the ALC briefed us on its tentative findings. The ALC had inspected 1,000 first stage blades and found 47 to be defective. A total of 893 second stage turbine blades were also inspected and 279 (31%) were found to be defective. ALC officials advised us that 10 of the defects identified in the second stage blades would present a potential safety problem if installed, and at least 4 of the 10 blades had a thin wall problem that could lead to catastrophic engine failure. Another 71 blades should have been returned to the manufacturer for replacement under warranty.

ALC officials have continued to reinspect the second stage blades and have reported various inspection results to us. The actual numbers of blades examined and the numbers of blades not meeting current technical standards has continually changed. With each reinspection, the number of defective blades has decreased. Air Force officials have stated that inspections by maintenance

personnel during final turbine reassembly will catch most of the defective blades, and thus preclude their installation in F100 engines.

ALC officials could not tell how many defective blades had been removed from scrap metal piles, returned to serviceable stocks, and/or used in the repair of F100 engines or engine modules at ALC or at bases around the world. ALC officials also do not know if defective blades were sent to the repair contractor directly from maintenance, or if they were removed from the scrap yard by the contractor after having been properly condemned by Air Force maintenance personnel.

AIR FORCE OFFICIALS HAVE
TAKEN CORRECTIVE ACTIONS

We kept ALC officials informed of our findings on this matter as they developed and briefed Department of Defense and Air Force officials at the Pentagon. The Air Force has taken a number of actions to prevent defective blades from being installed in engines and to correct underlying management control problems. Some of the major actions include:

- ALC began inspecting all stocks on hand of both first and second stage F100 engine blades repaired by the contractor.

- ALC is currently recalling uninstalled F100 first and second stage blades from field locations, worldwide, for reinspection.

-- ALC is developing guidelines for maintenance workers to help ensure that only properly condemned blades are sent to disposal. To prevent properly condemned blades from reentering the supply system, they have instructed that all condemned blades be mutilated before being sent to disposal.

-- Efforts are underway to obtain a complete accounting for all F100 blades received by the repair contractor.

These actions should solve the specific problems with the turbine blades. I should note, we found that other usable and needed F100 engine parts may have been prematurely condemned and sent to disposal. For example, an ALC official told us that while researching the blade problem, the ALC found that another major F100 engine component may also have been improperly condemned. We have also obtained evidence that parts for other aircraft engines have been prematurely sent to DRMO and later recalled from disposal. We will continue our review to determine the underlying causes for these internal control problems and whether the control weaknesses, with respect to the F100 engine blades, are systemic of other types of maintenance operations as well.

(390042)